PR001 26-Mar-12

Preliminary Report of Accident

U.S. Department of Labor

Mine Safety and Health Administration

~//

1. Accident Type:	2. Accident Classification				3. Date/Time of Accident 4. Date/I			4. Date/Time of De	ath	5. Fatal Case No
Fatal Injury	Electrical			03/23/201	03/23/2012 09:30 PM 03/2			10:45 PM	6	
6. Mine Information :					•			-		•
a) Mining Company Name		b) Mir	ne Name				c) Parent of Mining (Company	
Drummond Company Inc	Shoa	Shoal Creek Mine			Drummor			nd Company Inc		
7. Mine Location :		b) County			c) State 8. Mine			ID Number: 9. Union:		
Oakman			Jefferson			AL 0			1-02901 YES	
10. Primary Mineral Mined:	11. Nun	nber of plovees:	a) Total	o) Underground	c) O	pen Pit/	Quarry d) M	Iill/Prep Plant	e) Other	
BITUMINOUS COAL UN	ND MILLE EII	ipioyees.	689	601				88		
12. Contractor Name:				13. Union			ion	14. Contrac	ctor ID Number:	
15. Contractor Address:	ty	b) County			c) State			d) Zip Code		
16. Number of Contractor En	nployees:	a) Total	b)	Underground	c) Ope	n Pit/Qu	arry	d) Mill/Pr	ep Plant	e) Other
45.33	. TC: 0.1				140.37 1	a D	**	. 15		
17. Number of Persons in Min				0	18. Number					
	147	b) Contractor	Employees	s: 0	a) Mine E	mployees	s:	b) Co	ontractor Emp	
19) Location of Accident X 01-Underground		03-Open Pit		07-Advano	e Mining	30-N	1ill/Prep	Plant Oth	er (specify)	20. Mining Height: Feet Inches
02-Surface at Undergrou	ınd	06-Dredge Mi	ning	08-Retrea	Mining	99-0	office Fa			10 0
21. Nonfatal Injuries:	22.	Fatal Injuries:	-	T						
•		,	1							
23. Victim Information :	На	a) Name rold E. Ennis			b) Age 37					
c) Regular Job Title:			d) Activity	at Time of Acc					X N	line Employee
Electrician					Electrician					
•	eeks Days		Years Wee	ks Days			ırs Week	s Days		Years Weeks Days
a) Total: 3 2	8	b) at the mine:	3 28	c) a	t activity (23d)		1 29	· · · · · · · · · · · · · · · · · · ·	Contractor	
								26. Mine Telepho		
25. Autopsy Performed:	If Yes, Loca	ation						-	ne No.:) 617-3004	
25. Autopsy Performed: 27. Description of Accident (in			exact locati	on in the mine,	and status of res	cue and	recovery	(205		
	nclude equipm on 3/23/2012 , on the cabl	ent involved, the o	tely 2130 tle car, wh	hours, on the	: West Main Le ed fatal electric	eft section	on of th	operations): e Shoal Creek Mi electrician came) 617-3004 ine. The ele in contact w	ith the exposed 995
27. Description of Accident (in A fatal accident occurred performing electrical work	nclude equipm on 3/23/2012 , on the cabl	ent involved, the o	tely 2130 tle car, wh	hours, on the	: West Main Le ed fatal electric	eft section	on of th	operations): e Shoal Creek Mi electrician came) 617-3004 ine. The ele in contact w	ith the exposed 995
27. Description of Accident (in A fatal accident occurred performing electrical work	nclude equipm on 3/23/2012, on the cable in the cable	ent involved, the o	tely 2130 tle car, wh ent. The	hours, on the nen he receive disconnecting	e West Main Le ed fatal electric g device was n	eft sectii cal shoc ot locke	on of the	(205 operations): e Shoal Creek Mi electrician came agged out while t	ine. The ele in contact w his work was	vith the exposed 995 is being performed.
27. Description of Accident (in A fatal accident occurred performing electrical work volt energized cable leads The information provided in tregarding the cause of the acc 28. Equipment Manufacturer	nclude equipm on 3/23/2012, on the cable in the cable his notice is baident.	ent involved, the of the control of the control of a shutto reel compartment of the compartment of the control	tely 2130 tle car, whent. The	hours, on the nen he received disconnecting the table to the table the table the table table to the table ta	e West Main Le ed fatal electric g device was n ot represent final	eft sectii cal shoc ot locke	on of the k. The ed and t	(205 operations): e Shoal Creek Mi electrician came agged out while to	ine. The ele in contact w his work was	with the exposed 995 is being performed.
27. Description of Accident (in A fatal accident occurred performing electrical work volt energized cable leads The information provided in tregarding the cause of the acc 28. Equipment Manufacturer 30. District:	nclude equipm on 3/23/2012, on the cable in the cable his notice is baident.	ent involved, the of the control of the control of a shutto reel compartment of the compartment of the control	tely 2130 tle car, whent. The	hours, on the nen he received disconnecting the table to the table the table the table table to the table ta	e West Main Le ed fatal electric g device was n of represent final	eft sectional shocked to the section of locked	on of the k. The ed and t	(205 operations): e Shoal Creek Mi electrician came agged out while to	ine. The ele in contact whis work was	with the exposed 995 is being performed.
27. Description of Accident (in A fatal accident occurred performing electrical work volt energized cable leads The information provided in tregarding the cause of the acc 28. Equipment Manufacturer 30. District: C1100 Birmi 34. Accident Investigator:	nclude equipm on 3/23/2012, on the cable in the cable his notice is baident.	ent involved, the of the control of the control of a shutto reel compartment of the compartment of the control	tely 2130 tle car, whent. The	hours, on the nen he received disconnecting the table of table o	e West Main Le ed fatal electric g device was n of represent final o)	eft sectional shocked to the section of locked	on of the k. The ed and t	(205 operations): e Shoal Creek Mi electrician came agged out while to	of the inciden C32-56CX-5 nt Number: 4495	with the exposed 995 is being performed. In the exposed 995 is being performed.
27. Description of Accident (in A fatal accident occurred performing electrical work volt energized cable leads The information provided in tregarding the cause of the acc 28. Equipment Manufacturer 30. District: C1100 Birmi	nclude equipm on 3/23/2012, on the cable in the cable his notice is baident.	ent involved, the of the control of the control of a shutto reel compartment of the compartment of the control	tely 2130 tle car, whent. The	LY and does not be the second disconnection of the second	e West Main Le ed fatal electric g device was n of represent final o)	eft sectional shocked to the section of locked	on of the k. The ed and t	egarding the nature 105 33. Evel	of the inciden C32-56CX-5 nt Number: 4495	with the exposed 995 is being performed.
27. Description of Accident (in A fatal accident occurred performing electrical work volt energized cable leads The information provided in tregarding the cause of the acc 28. Equipment Manufacturer 30. District: C1100 Birmi 34. Accident Investigator: Joseph P. Turner 36. Type of Report:	nclude equipm on 3/23/2012, on the cable in the cable his notice is baident.	ent involved, the of the control of the compartment of a shuth reel compartment of the co	ry data ON (Joy Mar Field Office	LY and does not be the second disconnection of the second	e West Main Le ed fatal electric g device was n of represent final o) mer AL rson Notified: Weekly ed:	eft sectional shocked to the section of locked	on of the k. The ed and t	egarding the nature 105 33. Evel	of the inciden C32-56CX-5 nt Number: 4495	at or conclusions Time 09:45 P